



MS314 .50 ct. Cushion 1 Dia.x.50=.50 ct. 6.5 Gr. (4.5x4.5mm)
MS314 .75 ct. Cushion 1 Dia.x.75=.75 ct. 7.0 Gr. (5x5mm)
MS314 1 ct. Cushion 1 Dia.x1.00=1.00 ct. 7.0 Gr. (5.8x5.8mm)
MS314 1.5 ct. Cushion 1 Dia.x1.50=1.50 ct. 8.0 Gr. (6.5x6.5mm)
MS314 2 ct. Cushion 1 Dia.x2.00=2.00 ct. 8.3 Gr. (7x7mm)